

Dike Conditions

The following pictures were taken during the flood event and after the flood event.



Tide water spilling over the dike and flowing across road during flood.



Note elevation difference between tide and flooded area and the erosion of the top of the dike



Water spilling over a northern section of dike adjacent to the road.



Water flowing over shoulder of road into deep ditch below the road. The ditch has been overtopped and saltwater is spreading across fields towards the west and south. The ditch drains to the north to Drainage District #5.



Sandbag patch at overflow location. Note driftwood log that was blocked by vegetation.



Another spill over location. Note upper level of dike has been eroded.



Combination concrete block, gravel and sandbag patch of eroded dike section

